<b>CCR No.</b> 96-0347	Logged Date	4/3/96	Rev.	Request T	Request Type	
Priority Routine	Urgent X E	mergency	Affected Release	FOS	Change Class	
Title (description) MSS Server for FOS EOC						
Documents Affected  Source Nos (RID, NCR, etc.) or Tech Reference						
VCATS, Baseline Manager		Refer	ence			
RTM Change Start New Baseline						
Problem Provide management services for FOS EOC using MSS. Integration and test needs to be completed by 15 April 1996.						
Proposed Solution  1. Assign Eagle as MSS Server. Assign 2.5 GB drive from Hydra to Eagle. Upgrade Eagle memory to 256 MB.  2. Verify 2.5 GB drive (from Hydra) operation due to reported poor shipping practices from GSFC  3. Install minimum software as identified by Release A MSS. Installation by HTSC/EDS. List of software attached.  4. Software configured by Release A MSS. Release A MSS test.  5. Integration in permanent location by FOS/MSS team.						
Impact Analysis:						
Organizations Affected:	BOO	Contracts	ESO		x M&O	
QA Rel. A		Rel. IR1	MRS	SMO	Subconts	
_			area if needed. FOS			
Cost:	None	Small (Not exceeding		ledium 0,000 to \$500,000)	Large (Over \$500,000)	
Schedule:	None X Other MSS Server is option to mini-EOC					
Additional LOC	Additional LOC Man-Months 0.5					
Materials						
Originator Jacob Eisenstein						
	Sigr	nature			Date	
Office Office	ce Manager	nature			Date	
<b>Disposition</b> Approx		oproved w/Comm	ent For	ward	Disapproved	
Comments: Deferred 4/8 - Jeff G., Les W. & Darryl W talk about what liceses they do not have. Resolve version # w/Garry.						
CCB CI	hairperson	ure			Date	

CM01JU95 ECS